

GMB *bulletin* No.049

NEWS LETTER

DECEMBER 1 2011

AAPEX 2011 Las Vegas successfully closed.




Thank you, our old customers, new potential customers and GMB fans for visiting our booth at AAPEX during November 1-3, 2011.

We hope those visited our booth found anything new and interesting about GMB and have much more fun dealing with us.


AVAILABLE NOW

WATER PUMP

HONDA

WATER PUMP	TENSIONER & IDLER BEARING	CAR NAME	ENGINE MODEL	MODEL	YEAR
GWHO-62A 19200-RBC-003/013 	NA	CIVIC ACCORD TSX	K20A 2000	FD2 CL7	07.03-11.09 02.10-08.12


TOYOTA

WATER PUMP	TENSIONER & IDLER BEARING	CAR NAME	ENGINE MODEL	MODEL	YEAR
GWT-144A 16100-39465/6 	NA	COROLLA VOXY AVENSIS YARIS AURIS VITZ RAV4	2ZRFE 1800 2ZRFAE 2000 3ZRFE 3ZRFAE	ZRE142/142G ZRE144/144G ZRE152N/154N ZRR70G/70W	06.09-11.09 07.06-11.09

AUGUST.2011 SUPPLEMENT CORRECTION SHEET

PAGE#	MAKE	PART NO.	ERROR	CORRECTED TO
1	BMW	11 51 1 719 836	OEM# 11 51 1 719 836 = GWBM-09A	OEM# 11 51 1 719 836 = GWBM-08A

NEW DEVELOPMENT Universal Joint

GUIS-74 Application		OEM No	8-97945102-0		
Car Name	Model	Engine	CCM	Year→	←Year
ISUZU D-MAX					
Internal Circlip Type (Inside Snap) Thickness of Snap Ring : 1.5 mm Grease Fitting in Bearing Cap 					
January.2012					